

<p>The Rexroth Drive & Control Academy</p>	<p>Maintenance & Faultfinding for DKR (DIAX03) Spindle Drives with DriveTop</p>	
<p>SPN3</p>		
<p>Aims</p> <ul style="list-style-type: none"> • To provide the skills to maintain and fault find the system • To provide an understanding of the drive and control functions • To enable participants to configure the interface 		<p>Course Content</p> <ul style="list-style-type: none"> • Basic theory • Connections • Interface, typically analogue • Diagnostics • Drive configuration <p>Course equipment</p> <ul style="list-style-type: none"> • Full working simulators of model machines at a rate of 2 people per station, where possible
<p>Pre-requisites</p> <ul style="list-style-type: none"> • Participants should have an electrical and mechanical engineering background • Familiarity with IBM compatible PCs 		
<p>Participants</p> <ul style="list-style-type: none"> • Maintenance Engineers • Control engineers • OEM engineers <p>Maximum number of attendees is four</p>		
<p>Notes</p>		